



Explanation

- 0 500 1000 Feet
- Proposed monitoring well
 - EPA monitoring well
 - Schlumberger monitoring well
 - Lear monitoring well
 - TCEQ monitoring well
- Total Cr above 10 µg/L
 - Total Cr above 50 µg/L
 - Total Cr above 100 µg/L

				WEST COUNTY ROAD 112 GROUND WATER PLUME SITE MIDLAND COUNTY, TEXAS		Proposed Additional Monitoring Wells Location Map	
DESIGNED BY DWR	DRAWN BY CRS	CHECKED BY DWR	SCALE 1:12,000	DATE 08/30/2011	PROJECT NO EPA6.0000.05	FIGURE	